













G12 
4x25 x...(2)

K3 
10x50 x...(12)

M5 
8x35 x...(16)

G1 
6 x...(1)


G2 
4 x...(1)

G7 
4x35 x...(4)


P1 
x...(2)


N23 
M8x20 x...(8)

K2 
x...(8)

K8 
x...(8)


W3 
x...(1)


N7 
x...(4)

N13 
ø8x70 x...(4)






N2 
M6 x...(10)


K1 
x...(18)

K5 
x...(18)




II







IV




V




VI






VII





VIII





IX





X

 $A=B$ 




XI



XII



XIII



XIV

